

# Beam summary data in MR Run42 (T2K Run3c)

A.Murakami for beam group

# Overview

- Apply the Good spill selection to the beam data in the MR Run42
  - Use improved fitting for horn current (by Suzuki-san)
  - Used data set : Beam line Run# **420022 (4/8) ~ 420212 (5/5)**
- Horn current setting in this period : **250kA**

# Spill selection

1. Physics run
  - “run\_type” is “physic run” and all Horn ON
  - exclude spills for beam tuning, beam study
2. TriggerFlag is “Beam Trigger” (beam during MR operation)
3. Good GPS status
4. CT05 # of protons per spill  $> 1e11$  in order to exclude spills which no beam in MR (due to machine interlock etc...) **Quick spill selection**
5. Normal condition cut
  - exclude unusable spills (e.g. PV2 magnet unstable etc...)
6. Horn current cut
  - Nominal current  $\pm 5$  kA for all three horns
7. MUMON cut
  - beam angle within 1mrad ( $|Si\ fit\ X| < 10cm$  &  $|Si\ fit\ Y| < 10cm$ )
  - Si total Q / CT05 cut : mean of Q/CT05  $\pm 5\%$  **Good spill selection**

# Horn & MUMON cut

- Horn current & MUMON Si Q /CT5 cut are defined as the followings table.
  - Horn cut : (Mean of three horns current in physics run)  $\pm 5$  kA
  - MUMON SiQ / CT5 cut : (Mean of this ratio in physics run)  $\pm 5\%$

run#	Horn current setting	Horn current cut	MUMON SiQ/ CT5 cut
420022~420212	250kA	$249.5 \pm 5$ kA	$32.14 \pm 5\%$


# Normal condition cut

- Remove 1 spill by normal condition cut
  - Run#420189, Spill#3032400 : Neutrino BLM MPS

# GPS Status

Graph

$|GPS1-GPS2| < 200\text{ns}$




GPS1,2 status are good during this period

No Bad spill


# Horn current

**249.5 ± 5kA**


Horn1 current



Horn2 current




Horn3 current



- No bad spill, but horn current decreasing gradually (especially from Apr/29)
- But, current is stable from 5/3

# Horn current decreasing

Horn1 current




Waring for NU2 temperature at 4/29 13:38 (from shift summary)

*NU2 temperature was slowly rising. Air conditioner setting was too high. The setting was adjusted. Now it is stable.*

Other troubles at 4/29 are shown on backup page.

NU2 Temperature#1



Actually, NU2 temp. decreasing gradually from Apr/29



But, there seems to be no correlation b/w horn current and NU2 temp. in other time region(NU2 temp. rising in 4/22~4/26).

→ Other reason ? Anyway, be careful

\*This time scale is diff. from above plot **Day/Month** for horn current stability.

# MUMON Si fit center



Mumon Si fit-X



|fit center| < 10cm

No Bad spill

Mumon Si fit-Y




After beam restart,  
MUSi-y was about 1cm  
larger than MUSi-y  
before beam stop and  
decrease

# MUMON Si Q / CT05

Mumon Si Qtotal/CT5

$32.14 \pm 5\%$



**24 Bad spill** ( $\rightarrow$  increase from prev.(18 spills at 4/25 report) because mean of this ratio slightly decrease by including latest data)

$\rightarrow$  Still investigate the reason of bad spills

# Summary of Good spill selection (MR Run42)


**Run# 420022(4/8)~420212(5/5)**

	# of spills	Ratio
Physics spills	720980	1
Beam trigger	712202	0.988
Good GPS	712202	0.988
ppp(CT5)>1e11	711560	0.987
Normal beam	711559	0.987
Horn cut	711559	0.987
MUMON cut	711535	0.987

Bad spills during beam operation : **24 = 0.003%** of good spills

# of delivered protons (CT5) after Good spill selection :  
**6.583 e+19**

# Integrated POT (MR Run42)



# Definition of Good spill flag

- In order to distinguish the Horn-off spill from the horn ON spill, the value of the good flag will be re-defined.
  - flag =0 : Not suitable data for physics analysis.
  - flag =1 : Good spill for Horn 250kA operation.
  - flag =100 : Good spill for Horn OFF.
  - flag = 2, 3 ... 99: Reserved for the other horn operation mode.
  - flag =-1,-2 ... -99: Reserved for the other horn operation mode with opposite polarity.

horn current	0 kA	200 kA	250 kA
good spill flag	100	2	1

**T2K RUN1, 2, 3c : Flag = 1   T2K RUN3b : Flag = 2**

# Back up

# Neutrino Event/Trouble around 4/29 (from Shift summary)

4/26 Maintenance (10:00-21:00 MR injection Kicker)

[NU maintenance]

- + Horn CW: cover gas sampling, flushing
- + 32deg-CW: 4/20 by-pass of degasfier was open in TS-B2.
- + NU2 30deg CW: 4/27 AM Change broken strainer by new one.
- + DAQ maintenance: Control network maintenance: done.
- + NU3 CW: Low flow rate:
- + Slow-monitor maintenance:

4/29

4:22 DAQ abort

MIDAS status had no error. it was known case written in the shift manual. Alert was rest and run was changed.

5:35 Online Mon.

"MAG,PH3" is larger value (12.8A) than threshold. In plot, error bar was very large (+/-2A), but center value is almost zero.

Alert was reset and run was changed. It was informed to Nakadaira-san and Fujii-san.

13:38 Slow alarm

NU2 temperature was slowly rising. Air conditioner setting was too high. The setting was adjusted. Now it is stable.

4/30 21:01 NU MPS Horn current balance

- > checked -> no problem
- > 21:47 Horn recovered
- > 21:53 beam is back

5/2 10:00-12:00 MR study

5/2 11:30 Horn CW He sampling

- > Stop horn operation during sampling work.

# Bad spills by mumon/ct cut

The list of 24 bad spills by mumon/ct cut

**Run# Event# Spill# : MUMON SiQ / CT05 [nC/1e12 pot]**

420129 399 2787394 : 33.8941  
420131 4245 2792766 : 34.0369  
420131 6614 2795135 : 33.8097  
420131 6690 2795211 : 33.7969  
420133 99 2802369 : 33.8241  
420133 282 2802552 : 34.3632  
420133 365 2802635 : 34.0714  
420133 842 2803112 : 34.3079  
420133 1663 2803933 : 33.9289  
420133 1981 2804251 : 33.8019  
420133 2736 2805006 : 34.3291  
420133 3397 2805667 : 34.2762  
420133 3744 2806014 : 34.1580  
420133 3781 2806051 : 33.8342  
420133 3975 2806245 : 33.9332  
420133 4121 2806391 : 33.8077  
420133 4359 2806629 : 33.8676  
420133 4409 2806679 : 34.2070  
420133 4540 2806810 : 33.8394  
420133 5709 2807979 : 34.0246  
420133 5883 2808153 : 33.7843  
420133 5893 2808163 : 34.0234  
420133 6015 2808285 : 33.7949  
420133 6067 2808337 : 34.3270

Now investigate the reason of these bad spills. At this moment, these spills are still “Bad”.